



SPECIFICATIONS:

- ◆ Model no.: V10 Diving Light
- ◆ Bulb: CREE XM-L2 U2 (Max 860 lumens)
- ◆ Color temperature: 6500 K
- ◆ Runtime: high 90 min, low 150 min, SOS 120 min
- ◆ Output levels: high > low > SOS
- ◆ Reflector: glossy aluminum reflector
- ◆ Lens: 4 mm toughened glass
- ◆ Body material: durable aircraft-grade aluminum
- ◆ Angle of light beam: 16° hot spot
- ◆ Surface treatment: premium anodizing
- ◆ Color: Black / Red / Blue
- ◆ Battery: 18650 Li-ion battery * 1
- ◆ With battery over-discharging protection, polarity reversing protection
- ◆ Operation voltage: 4.2 V to 3.0 V
- ◆ Waterproof: 60 Meters underwater
- ◆ Dimensions: 135 mm (length) * 28 mm (dia. of lamp head) * 26 mm (dia. of lamp body)
- ◆ Weight in air: ca. 105 g. (without battery); ca. 154 g. (with battery)
- ◆ Underwater weight: ca. 80 g. (with battery)
- ◆ Package drop test height: 1.5 Meters

POWER INDICATOR:

Ring-shaped power indicator surrounding the switch lights up in green, or yellow, or red, when voltage is above 70%, or between 70-40%, or between 40-10%. It flashes in red for voltage between 10-5%, and turns off when voltage is below 5%.

LOW BATTERY WARNING:

The light flashes 3 times if the battery voltage is less than 10%; it repeats after 5 seconds, and then switches to lower brightness. The light switches off when the voltage is less than 5%.

BATTERY INSTALLATION:

1. Unscrew the lamp head, holding it pointing upward.
2. Remove used battery and replace with fresh one per polarity signs.
3. Screw lamp head down. Do not overtighten to break the O-ring.

BATTERY CHARGING:

1. Put the battery in the slot of the charger.
2. Plug charger in the wall power socket. The indicator light of charger lights in red. If the battery is not fully charged; it lights in green after the battery is fully charged, or when the charger is at free-load status.
3. Unplug the charger, take the battery out, and install it into the light for usage.

MODES CHANGING:

Successively click the switch ON-OFF to cycle through high, low, SOS, and off.

⚠ CAUTION:

1. Never attempt to repair or modify the light yourself.
2. Please handle illuminants with care, to avoid breakage. Illuminants can break or splinter when banging against the device. Splinters can cause eye and skin injuries. Check the light regularly for sharp edges, scratches or damages to the surface or O-ring, as this can cause the light to flood under pressure. PLEASE LUBRICATE THE THREADS, O-RING GROOVE WITH SILICONE GREASE TIMELY.
3. Please rinse the product surface thoroughly after each use. Allow sufficient time to dry both inside and outside before storage.
4. Please remove the battery for transport or storage. Do not lay the battery in a fire or expose it to direct heat. Do not wet or hit the battery. Please charge the battery after each use, or once every three months, to avoid over-discharging.
5. Never leave the light unattended when it is on.
6. Please keep the device out of the reach of children or pets.
7. Never shine the light to human or pet's eye.

WARRANTY RETURN POLICY:

Please contact your local distributor or retailer for information on how to handle your warranty items.